





Terberg volvo-terberg palfinger 4x4

Allgemeine Merkmale

Marke	Terberg
Unterkategorie	Bohranlage
Farbe	Orange
Zustand	Gebraucht
Allgemeinzustand	Gut
Kraftstoff	Diesel



Terberg volvo-terberg palfinger 4x4

Beschreibung

VOLVO-TERBERG 4X4 PALFINGER CRANE runs and work fine, the truck have no documents, original from holland, tyre goed engine gearbox good direct ready for work, can be dillivered including drilling rig compleet with drilling head brand bomag made in germany at extra cost, to fix the machine on the truck is for the buyer, prices on request. Holland Trading Transport and Repair by Korte Venen 28 Steenwijk 8331 TH Netherlands request mail. us info@holland-trading.com more foto s see the web site www.holland-trading.com call william +31.641883344 of oene +31.653862003

Zubehör